Outstanding Items & Suggestions from the 4pi Workshop May 15-17, 2005 in Berkeley

May 22, 2005 Revised June 18, 2005

Please send any question or omissions to: kmheeger@lbl.gov

Deployment Procedures (lead: Fred)

- 1.Include step to put control panel into "safe mode" during computer control of 4pi system.
- 2. Removal of cable 2 weight (only a procedural modification).

Software (lead: Fred)

- 1.Additional dialog box for "Go" button. -> done for z-axis system; consider doing something similar for off-axis mode
- 2. Evaluate additional terms to be included in calculation of position of pole: width of pivot block, buoyant forces, weight of cables.
- 3. Change definition of theta_pole to be in Herb's coordinate system, i.e. relative to the vertical rather than the horizontal.
- 4.Implement Jordan's watchdog circuit.
- 5.Insert real detector geometry into control program.
- 6.Adjust serial cables to motor drives so that motor 1 and motor 2 are independent. -> waiting on correct cables
- 7. Add feature to disable instrumentation unit readout in case of failure.
- 8. Provide easier access to history information.
- 9. Write more documentation.

Parts to Order (lead: Andrew)

- 1. Manual control panel RP240.
- 2.Spare motor controller and drive.
- 3.2x MDC 450006 + bolts and viton gaskets
- 4. Double Bubble orange and other epoxy.

Instrumentation Unit Redesign and Testing(lead: Lindley)

- 1. Obtain padded safe box for shipment of instrumentation units.
- 2. Redesign lucite enclosure and establish better sealing procedure with epoxy.
- 3. Test new design of diffuser balls.
- 4. Conduct suite of pressure, mechanical, and electrical tests at LBNL.
- 5. Prepare soak tests of epoxy samples.
- 6. Characterize all instrumentations units.

Commissioning Tests at LBNL (lead: Andrew, Fred, Karsten)

- 1. Complete survey of pole positions when deployed.
- 2.Can we disengage and turn the lower spool (cable 2) without opening the glovebox?
- 3.Is the pole deflected off center from the stiffness of the cables? Measure the deflection of the pole when deployed?
- 4. Additional pole deflection measurements and calculations.

Outstanding Hardware Items (lead: Karsten)

At LBNL

- 1.Relocation of limit switch to somewhere that minimizes interference with pole assembly, perhaps with the ability to swing it out of the way for the off-axis mode.
- 2. Modification of anti-rotation pins on pin block to provide more stability.
- 3. Addition of location to store weighted segment on pole hanging rack.
- 4. Back-cutting of upper pulley mounting bracket to allow the IU connector to clear.
- 5. Weld pins on cable 2 attachment segment. -> douuble check
- Flexible source cage.
- 7. Capture screw on pivot block.
- 8. Design enclosure for chimney cameras
- 9. Mockup of bird cage opening -> in progress
- 10. Complete cable marking
- 11. Nylon covers for D-sub connectors in glove box. -> in progress
- 12. Viton gaskets for ports and motor cover.
- 13. Shaft seal for clean tent ceiling.
- 14. Cable conduit inside penthouse.
- 15. Deployment holder for 4 instrumentation units.

Before shipment to Japan

- 1. Weld motor power feedthroughs into drive plate.
- 2. Attachment for glove box CCD camera in penthouse.

On-Site

1. Weld axial support to penthouse.

On-Site Preparations (lead: Karsten)

- 1.Do we need additional clearance measurements for the 4pi chimney cameras?
- 2. We may want to double-check the bolt pattern of the glovebox/penthouse interface.

On-Site Soak tests and counting (lead: Karsten)

- 1.MDC window for chimney cameras.
- 2.Extra cable samples.
- 3. Soak tests of epoxy and Lucite-nylon and Lucite-stainless joints.

Documentation (lead: Karsten)

- 1. Complete set of drawings.
- 2.Document for fire station.
- 3.Deployment procedures.
- 4. Cabling document.
- 5. Revise commissioning plan.

Cleanliness

1. How do we clean the clevis pins with the spring loaded ball?

Other Questions & Suggestions

- 1. Have we observed any work hardening of cable during LS soak?
- 2. What about the radon permeability of lucite windows?
- 3.Is the strength of the pole affected by extra holes in each pole segment?
- 4. Should have additional nylon lanyard for in-pole source pins.
- 5. What about fire safety of D-sub connectors in glovebox.
- 6. Should have cable marking: near top of retraction, at all pivot block locations, and at regular intervals.
- 7. Should have cable marking that indicates when pole is horizontal.
- 8. We may want to try imaging an object at the detector center with the spotlights on with the CCD cameras.